

POOL INSPECTION REPORT

Inspection ID: 26 Pool Name: Vineland Community Pool Pool Address: 301 S. East Boulevard

Inspection Year: 2016

[Rating 1]

Rating 1: Satisfactory - 07/05/2016

[Rating 2]

Rating 2: Satisfactory - 08/04/2016

Comments: